

INSPECTION REPORT

Michael O. Leavitt Governor

Kathleen Clarke Executive Director

Lowell P. Braxton Division Director 1594 West North Temple, Suite 1210 PO Box 145801

Salt Lake City, Utah 84114-5801

801-538-5340 801-359-3940 (Fax) 801-538-7223 (TDD) Partial: XXX Complete: Exploration: Inspection Date & Time: 8/16/2000 / 8:30a.m.-1:30p.m.

Date of Last Inspection: 7/27/2000

Mine Name: Trail Mountain Mine County: Emery Permit Number: ACT/015/009						
Permittee and/or Operator's Name: PacifiCorp						
Business Address: P.O. Box 310, Huntington, Utah 84528						
Type of Mining Activity: Underground XXX Surface Prep. Plant Other						
Company Official(s): Dennis Oakley, Chuck Semborski						
State Officials(s): Bill Malencik Federal Official(s): None						
Weather Conditions: Clear, Rained at Mine Site on 8/15/2000						
Existing Acreage: Permitted-4178 Disturbed-10.7 Regraded-Seeded-Bonded-10.7						
Increased/Decreased: Permitted Disturbed Regraded Seeded Bonded						
Status: _Exploration/_XXX_Active/_Inactive/_Temporary Cessation/_Bond Forfeiture						
Reclamation (_Phase I/_Phase II/_Final Bond Release/_LiabilityYear)						

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

Instructions

- Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For <u>complete inspections</u> provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.

b. For partial inspections check only the elements evaluated.

- 2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

1. 2. 3.	PERMITS, CHANGE, TRANSFER, RENEWAL, SALE SIGNS AND MARKERS TOPSOIL	EVALUATED [XX] [XX] [XX]	<u>N/A</u> ∐ ∐ ∐	COMMENTS [XX] L]	NOV/ENF
4.	HYDROLOGIC BALANCE:	[VV]	r' a	(VV)	f 1
a.	DIVERSIONS SEDIMENT PONDS AND IMPOUNDMENTS	[XX] [XX]	ᆛ	[XX] [XX]	<u> </u>
b. с.	OTHER SEDIMENT CONTROL MEASURES		片		뒴
d.	WATER MONITORING		븁	[]	盲
e.	EFFLUENT LIMITATIONS		급	<u>[XX]</u>	Ti.
5.	EXPLOSIVES	[]	Ħ	[]	<u> </u>
6.	DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES	11	Ħ	<u> </u>	
7.	COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS	$\overline{[XX]}$	\Box	\Box	\Box
8.	NONCOAL WASTE	$\overline{[XX]}$	\Box	$\overline{[XX]}$	\Box .
9.	PROTECTION OF FISH, WILDLIFE AND				
	RELATED ENVIRONMENTAL VALUES	\Box	\Box	· []	\Box
10.	SLIDES AND OTHER DAMAGE		\Box		
11.	CONTEMPORANEOUS RECLAMATION				Ц
12.	BACKFILLING AND GRADING	\Box	Ц	ĹΪ	Ц
13.	REVEGETATION	Ц	Ц		Ц
14.	SUBSIDENCE CONTROL	Щ	ГŢ	Ļ	딘
15.	CESSATION OF OPERATIONS	Ш	Ш	Ш	ш
16.	ROADS:	FT.TT.7	r 1	r 1	r a
a.	CONSTRUCTION/MAINTENANCE/SURFACING	[XX]	H	Ц	<u> </u>
_b.	DRAINAGE CONTROLS	[XX]	H	[]	니
17.	OTHER TRANSPORTATION FACILITIES		Ӊ	LI IVVI	<u> </u>
18.	SUPPORT FACILITIES/UTILITY INSTALLATIONS	[XX]	닏	[XX]	<u> </u>
19.	AVS CHECK (4th Quarter-April, May, June)(date)		H	<u> </u>	디
20.	AIR QUALITY PERMIT		니	<u> </u>	<u> </u>
21	RONDING & INSURANCE	1 1	1 1	1 1	1 1

INSPECTION REPORT

(Continuation sheet)

Page <u>2</u> of <u>3</u>

PERMIT NUMBER: ACT/015/009

DATE OF INSPECTION: 8/16/2000

(Comments are Numbered to Correspond with Topics Listed Above)

1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE

The permit embraces 3,538.98 acres, of which 10.7 acres are disturbed. The reclamation agreement is on file and is dated April, 1992.

No new amendments have been submitted to the Division.

4A. HYDROLOGIC BALANCE: DIVERSIONS

Two undisturbed culverted diversions are in place. Cottonwood Creek is the only perennial diversion. There is one undisturbed concrete diversion that collects and routes runoff to the sediment pond. The culverts and concrete ditch were functional. Water was reporting to the concrete ditch from the tipple wash process.

4B. HYDROLOGIC BALANCE: SEDIMENT PONDS AND IMPOUNDMENTS

The sediment pond lies immediately below the mine site. This provides the sediment control for the majority of the disturbed area. The pond was cleaned last fall.

The sediment pond was not discharging; no hazardous conditions were noted during the inspection.

4C. HYDROLOGIC BALANCE: OTHER SEDIMENT CONTROL MEASURES

There are two BTCA areas; one is located above the parking lot. The other lies below the sediment pond. Both appeared to be functioning as designed.

4E. HYDROLOGIC BALANCE: EFFLUENT LIMITATIONS

The mine was discharging mine water into the permitted undisturbed drainage. The meter was jumping between 200 and 300 GPM. Dennis Oakley took samples and recorded the volume at 250 GPM.

INSPECTION REPORT

(Continuation sheet)

Page <u>3</u> of <u>3</u>

PERMIT NUMBER: ACT/015/009

DATE OF INSPECTION: 8/16/2000

(Comments are Numbered to Correspond with Topics Listed Above)

8. NONCOAL WASTE

All noncoal waste which is generated by the operational stage is temporarily stored on the surface. It is permanently disposed of at a land fill. A used oil container is adjacent to the fuel storage within a concrete containment structure.

Some litter was observed in the parking lot. It will be removed by the permittee.

18. SUPPORT FACILITIES-

No new support facilities have been permitted for the mine site.

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas, and Mining.

Copy of this Report:

Mailed to: Chuck Semborski (PacifiCorp)

Given to: Pam Grubaugh-Littig (DOGM)

Henry Austin (OSM)

Filed to: Price Field Office

Date: August 17, 2000

Inspector's Signature: 426

Wm. J. Malencik